
AXIAL FAN - EC Motor

LWAE3G710SS-5PEW-05-00

Wiring Diagram

NO.	Function	Functional description	NO.	Function	Functional description
PE	PE	Ground lead	P3	4~20mA	Analogue control input 4~20mA
P1	N	Naught line		20V	Fixd voltage out 20VDC
				10V	Fixed voltage output 10VDC
	L	Live line		0~10V/PWM	Speed regulation signal input terminal, 0~10V or PWM
				GND	Ground reference end of control signal
P2	NO	Status relay, normally open; close with error		FG	Speed Signal Feedback
	COM	Status relay, common connection		RS485A	Bus connection RS485; RSA; MODBUS RTU
	NC	Status relay, normally turn-off; break with error		RS485B	Bus connection RS485; RSB; MODBUS RTU



Label

Confirm by sales team when placing sample order or bulk order